



Features

- Professional industrial strength tool.
- For roof felt, insulation, housewrap, and vapor barrier
- Quick jam clearing - no tool required
- Easy access to staple track
- Wide trip lever with smooth, rolled edge
- Holds 168 Staples

Staple Loading

- 1) Use only Paslode 5000 Series staples.
- 2) Lift the handle lid.
- 3) Pull the feed spring back and disengage from pusher.
- 4) Slide two strips of staples onto the rail through the back of the tool.
- 5) Engage spring back onto pusher hook.



Jam Clearing

- 1) Disengage feeder spring, and remove all staples.
- 2) Pull up on round head pin and swing trip lever out of the way.
- 3) Unhook the front jaw by releasing spring wire form.
- 4) Slip the front jaw off of the tool. Clear any jammed staples.
- 5) Reverse this process to reassemble the tool.

